RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11369

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080034-6

RECEIVED FROM

California Rubber Products, Inc.

DATE REC'D 2-25-57

P.O. NO. 69223

VENDOR PACKING SLIP NO. 3503

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	000000	12253	0	0	00	00	02		

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
125 Ft.	730155-070 Rubber Hose, Neoprene 3/8" Inside Diameter X 1/8" 50-60 30-40 Flare	125		
	To supersede Insp. & Rej. Report #11251			

RECEIVED BY

INSPECTED BY Dma DATE 2/25/57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1068

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11373

RECEIVED FROM

Globe Electrical Mfg. Co.

DATE REC'D 225-57

P.O. NO. 64414

VENDOR PACKING SLIP NO. 6143

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	000000	12073	0	0	00	00	02		

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
10	730125-021 Relay, PST, 15 AMP, Globe #2650556	10		

RECEIVED BY

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080034-6

INSPECTED BY DMA DATE 2/25/57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1068